



700-HRQ2HA22

Tube Base Dial Timing Relay

[Print](#) [Share](#) [QR code](#)

Lifecycle status: Active

[ADD TO BOM](#)

[Get Support](#)

| | | |
|--------------------------|---|--|
| Technical Specifications | Nominal current | 5 A |
| General | Suitable for DIN rail (top hat rail) mounting | False |
| Mechanical | Degree of protection | IP40 (panel surface) |
| Construction | Shock resistance | Malfunction: 98 m/s ² (10 G) |
| Electrical | | Malfunction: 10...55 Hz with 0.5 mm double Amplitude each in three directions for ten minutes each |
| Environmental | Vibration resistance | |
| Drawings | Dielectric strength | Pole-to-pole: 2000V AC @ 50/60Hz for 1 min |
| Documents | | |
| Accessories | Suitable for front mounting | False |
| Alternative Products | With plug-in socket | False |
| Technotes | | |

Contact your distributor in
Burlington
[Change location](#)



[Find a partner](#) >



Copyright ©2025 Rockwell Automation, Inc.