
SIEMENS

Data sheet

3RA2913-3DA1

Wiring module top for contactor assembly S00 without gap between the Contactors, screw terminal



Further information


Siemens has decided to exit the Russian market (see here). down-russian-business https://press.siemens.com/global/en/pressrelease/siemens-wind-Siemens is working on the renewal of the current EAC certificates. Please contact your local Siemens office on the status of validity of the EAC certification if you intend to import or offer to supply these products to an EAC relevant market (other than the sanctioned EAEU member states Russia or Belarus). Information on the packaging https://support.industry.siemens.com/cs/ww/en/view/109813875 Information- and Downloadcenter (Catalogs, Brochures,...) https://www.siemens.com/ic10 Industry Mall (Online ordering system) om/mall/en/en/Catalog/product?mlfb=3RA2913-3DA1 https://mall.industry.siemens.c


Cax online generator

http://support.automation.siemens.com/WW/CAXorder/default.aspx?lang=en&mlfb=3RA2913-3DA1

Service&Support (Manuals, Certificates, Characteristics, FAQs,...)

https://support.industry.siemens.com/cs/ww/en/ps/3RA2913-3DA1 Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, EPLAN macros, ...) http://www.automation.siemens.com/bilddb/cax_de.aspx?mlfb=3RA2913-3DA1&lang=en





last modified:

6/17/2021 🖸