

Harmony GTO, 12.1 inch installation gasket HMIGTO Stainless

HMIZG562

- Uscontinued on: Mar 13, 2024
- ! To be end-of-service on: Jun 30, 2032

Product availability: Non-Stock - Not normally stocked in distribution facility

Price*: 270.00 USD

Main

Range of Product	Harmony GTO
accessory / separate part type	Seal
Accessory / separate part category	Protection accessory
Product or Component Type	Gasket

Complementary

Product Compatibility Advanced touch panel

Ordering and shipping details

Category	US10MC222569
Discount Schedule	0MC2
GTIN	3595864150574
Returnability	No
Country of origin	JP

Packing Units

Unit Type of Package 1	PCE
Number of Units in Package 1	1
Package 1 Height	0.079 in (0.200 cm)
Package 1 Width	12.008 in (30.500 cm)
Package 1 Length	15.748 in (40.000 cm)
Package 1 Weight	4.409 oz (125.000 g)
Unit Type of Package 2	S03
Number of Units in Package 2	30
Package 2 Height	11.811 in (30.000 cm)
Package 2 Width	11.811 in (30.000 cm)
Package 2 Length	15.748 in (40.000 cm)
Package 2 Weight	9.149 lb(US) (4.150 kg)

Price is "List Price" and may be subject to a trade discount – check with your local distributor or retailer for actual price.

Contractual warranty

Warranty

18 months

Sustainability

Green PremiumTM label is Schneider Electric's commitment to delivering products with best-inclass environmental performance. Green Premium promises compliance with the latest regulations, transparency on environmental impacts, as well as circular and low-CO₂ products.

Guide to assessing product sustainability is a white paper that clarifies global eco-label standards and how to interpret environmental declarations.

Learn more about Green Premium >

Guide to assess a product's sustainability >

Well-being performance

Rohs Exemption Information	Yes
Eu Rohs Directive	Pro-active compliance (Product out of EU RoHS legal scope)
	EU RoHS Declaration
China Rohs Regulation	China RoHS declaration
California Proposition 65	"WARNING: This product can expose you to chemicals including: Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov"